# Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2016-P-00141

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513					
Exit Meeting Contact: Robert Roth	Total Man Days: 3					
Pipeline Safety Representative(s): Donald Hankins						
Company Representative to Receive Report: Michael Fuller	Emailed Date:					
Company Representative's Email Address: mfuller2@ameren.com	04/08/2016					

#### **Inspection Summary**

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Record Audit	Maryville	Donald Hankins	Maryville	3		Chuck Tebbe, Robert Roth

#### **Statement of Activities**

On April 5-7, 2016, a record audit was conducted at Ameren Illinois, in Maryville, Illinois, to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590. The audit included a review of company documents regarding the specific code sections as identified on the attached inspection form.

Staff reviewed paper records for the year of 2014. No deficiencies were identified by Staff during the review of the paper records.

#### **Exit Statement**

# INSPECTION FINDINGS

# **Standard Inspection - Record Audit**

# Issues(s) Found:

[NO ISSUES FOUND]

## Notice Of Amendment(s) Found:

[NO NOAS FOUND]

## Notice Of Violation(s) Found:

[NO NOPVS FOUND]

# PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

### Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

# Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2016-P-00141

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]